


NOTES:

- W : DENOTES AUDIBLE WARNING
- Z(S) : DENOTES TX BERTH TO WOKING
- Y(S) : DENOTES RX BERTH FROM WOKING
- Z(W) : DENOTES TX BERTH TO FARNHAM
- Y(W) : DENOTES RX BERTH FROM FARNHAM
- Z(R) : DENOTES TX BERTH TO WOKINGHAM
- Y(R) : DENOTES RX BERTH FROM WOKINGHAM
- 1 : VDU ONLY DISPLAYED BERTH
- 2 : BLIND STORAGE BERTHS
- 3 : BERTH CLEARS 10 MIN. AFTER FROM BERTH CLEARS
- S : DENOTES RAPID ADDRESS BERTH

													
TESTER NAME		SIGNATURE		DATE	ACTIVITY	COMPLETE	DATE	Source Record Updated			National Records Group		
1					Prep. Inspection			Version	Prod.	Check			
2					Prep. W.C. and Cont			<div></div>			ELTHAM ASC ELTHAM TO LOCK SCHEMATIC		
3					Prep. S. & F./C.F.T.								
4					Cable core Loc. End								
5					Cable core Equ. End								
					Changeover Comp								
Complete tester details in your own check marking colour. Sign off for completed activities.										Issued	1 8 OCT 2013		
CAD GENERATED : ALTERATIONS TO BE MADE ON DESIGN FILE ONLY												CAD - A3, NR A3, v1.0	