



NOTES:

- W : DENOTES AUDIBLE WARNING
- Y(B) : DENOTES RX BERTH FROM BARNES
- Z(B) : DENOTES TX BERTH TO BARNES
- Y(K) : DENOTES RX BERTH FROM AW (FIRST CHAR. CHANGED FROM '0' TO 'F')
- Z(K) : DENOTES TX BERTH TO AW (FIRST CHAR. CHANGED FROM '0' TO 'F')
- 1 : VDU ONLY DISPLAYED BERTH
- 3 : BERTH CLEARS OUT 10 MIN AFTER FROM BERTH CLEARS
- S : DENOTES RAPID ADDRESS BERTH

TESTER NAME	SIGNATURE	DATE	ACTIVITY	COMPLETE	DATE	Source Record Updated	National Records Group
1			Prep. Inspection				
2			Prep. W.C. and Cont				
3			Prep. S. & F./C.F.T.				
4			Cable core Loc. End				
5			Cable core Equ. End				
Complete tester details in your own check marking colour. Sign off for completed activities.			Changeover Comp				
						Issued	17 AUG 2012

CAD GENERATED : ALTERATIONS TO BE MADE ON DESIGN FILE ONLY

NetworkRail

Drawing No
4TD-BS-3

Last Full
Correlation
Current
Version

Date
Ver.

NF1

CAD - A3 NR.A3 v1.0