

SIGNALS WITH CROSS BOUNDARY REMINDERS

(SIG1)

| | | |
|------------------|-------------------|-------------------|
| SSI 01 - SEVSIST | SSI 03 - TOTHAM | SSI 05 - CHESHUNT |
| NONE | NONE | S1395 |
| SSI 02 - BURYST | SSI 04 - BRIMDOWN | |
| NONE | NONE | |

SPAD ALARMS

☐ ALARMS

☐ UNACK

SIGNALLING ALARMS

☐ OUTSTANDING

ARS ALARMS

☐ OUTSTANDING

TRAIN DESCRIBER ALARMS

☐ OUTSTANDING

SYSTEM ALARMS

☐ OUTSTANDING

| | | | | | | | | | | | | | | | | |
|-------------|--|-----------|--|------|--|----------|----------------------|----------|------|-----------------------|------|-------|-----------------------|---|-------------------------------|---------|
| TESTER NAME | | SIGNATURE | | DATE | | ACTIVITY | | COMPLETE | DATE | Source Record Updated | | | Network Records Group | | Network Rail | |
| 1 | | | | | | | Prep. Inspection | | | Version | Prod | Check | | LIVERPOOL STREET SC WAGN IECC WORKSTATION 1 GPVDU MAP SIG1 | Drawing No A30LIV-IECCD-GP | |
| 2 | | | | | | | Prep. W.C. and Cont | | | GS1 | | | | | Sht No | MP8 |
| 3 | | | | | | | Prep. S. & F./C.F.T. | | | | | | | | Last Full | Date |
| 4 | | | | | | | Cable core Loc. End | | | | | | | | Correlation | Version |
| 5 | | | | | | | Cable core Equ. End | | | | | | | | Current | Version |
| | | | | | | | Changover Comp | | | | | | Produced | | | GS1 |
| | | | | | | | | | | | | | Checked | | | |
| | | | | | | | | | | | | | Issued | | | |

Complete tester details in your own check marking colour.
Sign off for completed activities.

CAD GENERATED : ALTERATIONS TO BE MADE ON DESIGN FILE ONLY

14/04/11

14/04/11