

•6 ROUTE NOT AVAILABLE AT THIS STAGE
•8 TRANSMIT TO GUILDFORD TD

ALL WASC BERTHS ARE TRANSMITTED TO SUBBITON NCP FOR TRUST AND SVS.

TYPICAL S:-

a)

The diagram shows a four-stage gas turbine engine. The stages are labeled X504, 0504, 0373, and X373. The flow is indicated by arrows. The 0504 and 0373 stages are connected by a shaft labeled 'a1'. The X504 and X373 stages are also connected by a shaft labeled 'a1'. The flow enters from the left, passes through X504, then 0504, then 0373, and finally exits through X373.



INTERLOCKING 6

0507	
ROUTE	TO BERTH
AISI	1216
BIM	0803
CIM	*6
DIM	0379

SOUTH WEST	
PAUL BRACK MAJOR PROJECTS DIVISION SOUTHERN GROUP LONDON	
Sft. No.	2
Version	CX1