
```

*
*      Filename      : STEP.PB      *
*
*      Data Version   : V12.3       *
*
*      Producer       [REDACTED]    *
*
*      Checker        [REDACTED]    *
*
*      Date           : 20/05/14     *
*

```

/*

Stepping Table file for signalbox code PB

Item	Berth	Characteristics	OCU	SYST	RXAD	S	[Trigger],Conditions

*/

```

0001:0261 N,S      TRBP
0002:                0267 N [TB10A19],TB10A18
0003:0263 N,S      TRBP

```

0004: 0269 N [TB8A9],TB8A8
0005: EVDF C TB8A12.-0269.-0273.-0277
0006:0266 N,S TRBP
0007: 0798 N [TB10A7],TB10A4
0008: 0796 N [TB10A7],TB10A9
0009: KXUS C TB10A4.-0798
0010: KXUF C TB10A9.-0796
0011:0267 N,S TRBP
0012: 0271 N [TB10B12],TB10B4
0013: COUT N [TB10B12],TB10B5
0014: EVDF C TB10B1.-0271.-0277
0015: EVDS C TB10A20.-0271.-0275
0016:0268 N,S TRBP
0017: 0796 N [TB7D3],TB7C16
0018: KXUF C TB7C16.-0796
0019:0269 N,S TRBP
0020: 0271 N [TB8A18],TB8A16
0021: 0273 N [TB8A18],TB8A15
0022: COUT N [TB8A18],TB8B18
0023: EVDF C TB8A13.-0273.-0277
0024:0270 N,S TRBP
0025: 0266 N [TB10A6],TB10A5
0026: KXUS C TB10A3.-0266.-0798
0027:0271 N,S TRBP
0028: 0267 N [TB10B11],TB10B9
0029: 0275 N [TB10B15],TB10B2
0030: 0277 N [TB10B15],TB10B3

0031:	0796 N [TB10B11],TB10B10
0032:	COUT N [TB10B8],TB10B7
0033:	EVDF C TB10B3.-0277
0034:	EVDS C TB10B2.-0275
0035:	KXUF C TB10B10.-0796
0036:0272 N,S	TRBP
0037:	0266 N [TB7D1],TB7C20
0038:	0268 N [TB7D1],TB7C19
0039:	KXUF C TB7C15.-0268.-0796
0040:0273 N,S	TRBP
0041:	0277 N [TB8A19],TB8A14
0042:	0796 N [TB8B1],TB8A20
0043:	EVDF C TB8A14.-0277
0044:	KXUF C TB8A20.-0796
0045:0274 N,S	TRBP
0046:	0270 N [TB9D7],TB9D6
0047:	KXUS C TB10A2.-0270.-0266.-0798
0048:0275 N,S	TRBP
0049:	0279 N [TB10B17],TB10B16
0050:	EVDS C
0051:0276 N,S	TRBP
0052:	0272 N [TB7C18],TB7C17
0053:	KXUF C TB7C14.-0272.-0268.-0796
0054:0277 N,S	TRBP
0055:	0281 N [TB8B3],TB8B2
0056:	EVDF C
0057:0278 N,S	TRBP

0058:	0274 N [TB9D6],TB9D5
0059:0279 N,S	TRBP
0060:	0283 N [TB10B18],TB10B17
0061:	E279 C
0062:0280 N,S	TRBP
0063:	0276 N [TB7C17],TB7C7
0064:	KXUF C TB7C13.-0276.-0272.-0268.-0796
0065:0281 N,S	TRBP
0066:	0285 N [TB8B4],TB8B3
0067:	E281 C
0068:0282 N,S	TRBP
0069:	0278 N [TB9D5],TB9D4
0070:	E282 C
0071:0283 N,S	TRBP
0072:	0287 N [TB10B19],TB10B18
0073:0284 N,S	TRBP
0074:	0280 N [TB7C7],TB7C6
0075:	E284 C
0076:	KXUF C TB7C12.-0280.-0276.-0272.-0268. -0796
0077:0285 N,S	TRBP
0078:	0289 N [TB8B5],TB8B4
0079:0286 N,S	TRBP
0080:	0282 N [TB9D4],TB9D3
0081:	EVUS C
0082:0287 N,S	TRBP
0083:	0291 N [TB10B20],TB10B19

0084:0288 N,S TRBP
0085: 0284 N [TB7C6],TB7C5
0086: EVUF C
0087: KXUF C TB7C12.TB7C10.-0284.-0280.
-0276.-0272.
-0268.-0796
0088:0289 N,S TRBP
0089: 0293 N [TB8B6],TB8B5
0090: FFDF C TB4A16.-0293.-0303.-0307.-0311.
-0315.-0319.-0323.-0327
0091:0290 N,S TRBP
0092: 0286 N [TB9D3],TB9C20
0093: EVUS C TB8B17.-0286
0094:0291 N,S TRBP
0095: 0301 N [TB10C1],TB10B20
0096:0292 N,S TRBP
0097: 0288 N [TB7C5],TB7C4
0098: EVUF C TB7B16.-0288
0099: KXUF C TB7C12.TB7C9.-0288.-0284.-0280.
-0276.
-0272.-0268.-0796
0100:0293 N,S TRBP
0101: 0303 N [TB8B7],TB8B6
0102: FFDF C TB4A18.-0303.-0307.-0311.-0315.
-0319.-0323.-0327
0103:0298 N,S TRBP
0104: 0290 N [TB9C20],TB9C19

0105: EVUS C TB8B16.-0290.-0286

0106:0300 N,S TRBP

0107: 0292 N [TB7C4],TB7C3

0108: EVUF C TB7B15.-0292.-0288

0109: KXUF C TB7C12.TB7C8.-0292.-0288.-0284.
-0280.
-0276.-0272.-0268.-0796

0110:0301 N,S TRBP

0111: 0305 N [TB10C3],TB10C2

0112:0302 D[0305] TRBP

0113: 0305 N (TB10C7+TB10C4).0302.-0305

0114:0303 N,S TRBP

0115: 0307 N [TB8B8],TB8B7

0116: FFDF C TB4A19.-0307.-0311.-0315.-0319.
-0323.-0327

0117:0304 N,S TRBP

0118: 0298 N [TB9C19],TB9C18

0119: 0310 N [TB9C17],TB9D1

0120: COUT N [TB9C17],TB9D2

0121: EVUS C TB8B15.-0298.-0290.-0286

0122:0305 D[0302],S TRBP

0123: 0309 N [TB10C8],TB10C7

0124: COUT N [-TB10C5],TB10C4

0125: FFDS C TB10D6.-0309.-0308.-0313.-0317.
-0321.-0325

0126:0306 N,S TRBP

0127: 0300 N [TB7C3],TB7C2

0128: 0310 N [TB7C1],TB7B20
0129: COUT N [TB7C1],TB6C13
0130: EVUF C TB7B13.-0300.-0292.-0288
0131:0307 N,S TRBP
0132: 0311 N [TB8B9],TB8B8
0133: FFDF C TB4A20.-0311.-0315.-0319.-0323.
-0327
0134:0308 D[0309] TRBP
0135: 0302 N [TB10C10],TB10C9
0136: 0309 N -0309.0308.(TB10C12+TB10C13
+TB10C15+TB10C16)
0137:0309 D[0308],S TRBP
0138: 0308 N TB10C9.0309.-0308
0139: 0310 N [TB10C17],TB10C13
0140: 0313 N [TB10C17],TB10C15
0141: 0315 N [TB10C17],TB10C16
0142: COUT N [TB10C17],TB10C12
0143: FFDS C TB10D7.-0313.-0317.-0321.-0325
0144:0310 N,S TRBP
0145: 0304 N [TB9C17],TB9C14
0146: 0306 N [TB9C17],TB9C15
0147: 0308 N [TB9C17],TB9C16
0148: 0316 N [TB9C10],TB9C12
0149: EVUS C TB8B13.-0304.-0298.-0290.-0286
0150:0311 N,S TRBP
0151: 0313 N [TB8B12],TB8B11
0152: 0315 N [TB8B12],TB8B10

0153: FFDF C TB4B1.-0315.-0319.-0323.-0327

0154:0312 N,S TRBP

0155: 0306 N [TB7B19],TB7B17

0156: 0308 N [TB7B19],TB7B18

0157: EVUF C TB7B12.-0306.-0300.-0292.-0288

0158:0313 N,S TRBP

0159: 0308 N [TB10D2],TB10C19.0313.-0308

0160: 0317 N [TB10D4],TB10C18

0161: COUT N [TB10C20]

0162: FFDS C TB11A1.-0317.-0321.-0325

0163:0314 N,S TRBP

0164: 0310 N [TB9C10],TB9C9

0165:0315 N,S TRBP

0166: 0319 N [TB8B20],TB8B19

0167: FFDF C TB4B2.-0319.-0323.-0327

0168:0316 N,S TRBP

0169: 0310 N [TB7B8],TB7B7

0170: 0312 N [TB7B8],TB7B6

0171: EVUF C TB7B11.-0312.-0306.-0300.-0292.
-0288

0172:0317 N,S TRBP

0173: 0321 N [TB10D5],TB10D4

0174: FFDS C TB11A2.-0321.-0325

0175:0318 N,S TRBP

0176: 0314 N [TB9C8],TB9C7

0177:0319 N,S TRBP

0178: 0323 N [TB8C1],TB8B20

0179: FFDF C TB4B3.-0323.-0327

0180:0320 N,S TRBP

0181: 0316 N [TB7B5],TB7B4

0182: EVUF C TB7B10.-0316.-0312.-0306.-0300.
-0292.-0288

0183:0321 N,S TRBP

0184: 0325 N [TB11A4],TB10D5

0185: FFDS C TB11A3.-0325

0186:0322 N,S TRBP

0187: 0318 N [TB9C7],TB9C6

0188:0323 N,S TRBP

0189: 0327 N [TB8C2],TB8C1

0190: FFDF C TB4B4.-0327

0191:0324 N,S TRBP

0192: 0320 N [TB7B4],TB7B3

0193: EVUF C TB7B9.-0320.-0316.-0312.-0306.
-0300.-0292.-0288

0194:0325 N,S TRBP

0195: 0329 N [TB11A5],TB11A4

0196: FFDS C

0197:0326 N,S TRBP

0198: 0322 N [TB9C6],TB9C5

0199:0327 N,S TRBP

0200: 0331 N [TB8C3],TB8C2

0201: FFDF C

0202:0328 N,S TRBP

0203: 0324 N [TB7B3],TB7B2

0204:0329 N,S	TRBP
0205:	0333 N [TB11A6],TB11A5
0206:	F329 C
0207:0330 N,S	TRBP
0208:	0326 N [TB9C5],TB9C4
0209:	F330 C
0210:0331 N,S	TRBP
0211:	0335 N [TB8C4],TB8C3
0212:	F331 C
0213:0332 N,S	TRBP
0214:	0328 N [TB7B2],TB7B1
0215:	F332 C
0216:0333 N,S	TRBP
0217:	0337 N [TB11A8],TB11A7
0218:0334 N,S	TRBP
0219:	0330 N [TB9C4],TB9C3
0220:	FFUS C
0221:0335 N,S	TRBP
0222:	0339 N [TB8C5],TB8C4
0223:0336 N,S	TRBP
0224:	0332 N [TB7B1],TB7A20
0225:	FFUF C
0226:0337 N,S	TRBP
0227:	0343 N [TB11A9],TB11A8
0228:0338 N,S	TRBP
0229:	0334 N [TB9C3],TB9C2
0230:	FFUS C TB9B18.-0334

0231:0339 N,S	TRBP
0232:	0345 N [TB8C6],TB8C5
0233:0340 N,S	TRBP
0234:	0336 N [TB7A20],TB7A19
0235:	0344 N [TB6C14],TB6D2
0236:	0353 N [TB6C14],TB6D1
0237:	FFUF C TB7A15.-0336
0238:0343 N,S	TRBP
0239:	0347 N [TB11A10],TB11A9
0240:0344 N,S	TRBP
0241:	0338 N [TB9C1],TB9B20
0242:	0340 N [TB9C1],TB9B19
0243:	0348 N [TB9A18],TB9A7
0244:	0353 N [TB9B16],TB9B1
0245:	FFUF H TB7A14.-0340.-0336
0246:	FFUS H TB9B17.-0338.-0334
0247:0345 N,S	TRBP
0248:	0347 N [TB8C9],TB8C8
0249:	0349 N [TB8C9],TB8C7
0250:0346 N,S	TRBP
0251:	0340 N [TB7A18],TB7A16
0252:	FFUF C TB7A13.-0340.-0336
0253:0347 N,S	TRBP
0254:	0351 N [TB11A19],TB11A11
0255:	0353 N [TB11A19],TB11A12
0256:0348 N,S	TRBP
0257:	0344 N [TB9A18],TB9A8

0258:0349 N,S	TRBP
0259:	0353 N [TB8C12],TB8C10
0260:0351 N,S	TRBP
0261:	0347 N [TB11A19],TB11A13
0262:	0347 N [TB11B2],TB11B1
0263:	0355 N [TB11B8],TB11B7
0264:	COUT N [TB11A19],TB11A14
0265:	COUT N [TB11B2],TB11A20
0266:0352 N,S	TRBP
0267:	0344 N [TB7A10],TB7A9
0268:	0346 N [TB7A10],TB7A8
0269:	FFUF C TB7A12.-0346.-0340.-0336
0270:0353 N,S	TRBP
0271:	0344 N [TB8C15],TB8C14
0272:	0346 N [TB8C15],TB8C13
0273:	0347 N [TB11A19],TB11A15
0274:	0347 N [TB8C15],TB11B4
0275:	0357 N [TB8C17],TB8C16
0276:	COUT N [TB11A19],TB11A16
0277:	COUT N [TB8C15],TB11B3
0278:0355 N,S	TRBP
0279:	0359 N [TB11B9],TB11B8
0280:0356 N,S	TRBP
0281:	0352 N [TB7A7],TB7A6
0282:	FFUF C TB7A11.-0352.-0346.-0340.-0336
0283:0357 N,S	TRBP
0284:	0361 N [TB8C18],TB8C17

0285:0359 N,S	TRBP
0286:	0363 N [TB11B10],TB11B9
0287:0360 N,S	TRBP
0288:	0356 N [TB7A6],TB7A5
0289:0361 N,S	TRBP
0290:	0365 N [TB8C19],TB8C18
0291:0363 N,S	TRBP
0292:	0367 N [TB11B11],TB11B10
0293:0364 N,S	TRBP
0294:	0360 N [TB7A5],TB7A4
0295:0365 N,S	TRBP
0296:	0369 N [TB9A2],TB8C19
0297:	HODF C TB8C20.TB8D1.-0369.-0373. -0377.-0381. -0385
0298:0367 N,S	TRBP
0299:	0371 N [TB11B12],TB11B11
0300:0368 N,S	TRBP
0301:	0364 N [TB7A4],TB7A3
0302:0369 N,S	TRBP
0303:	0373 N [TB9A3],TB9A2
0304:	HODF C TB8D1.-0373.-0377.-0381.-0385
0305:0371 N,S	TRBP
0306:	0375 N [TB11B17],TB11B12
0307:	HODS C TB11B13.-0375.-0379.-0383
0308:0372 N,S	TRBP
0309:	0368 N [TB7A3],TB7A2

0310:0373 N,S	TRBP
0311:	0377 N [TB9A4],TB9A3
0312:	HODF C TB8D2.-0377.-0381.-0385
0313:0375 N,S	TRBP
0314:	0379 N [TB11B18],TB11B17
0315:	HODS C TB11B15.-0379.-0383
0316:0376 N,S	TRBP
0317:	0372 N [TB7A2],TB7A1
0318:0377 N,S	TRBP
0319:	0381 N [TB9A5],TB9A4
0320:	HODF C TB8D3.-0381.-0385
0321:	HODS C TB8D6.-0381.-0385.-0383
0322:0378 N,S	TRBP
0323:	0376 N [TB9B7],TB9B6
0324:0379 N,S	TRBP
0325:	0383 N [TB11B19],TB11B18
0326:	HODS C TB11B16.-0383
0327:0380 N,S	TRBP
0328:	0376 N [TB9B8],TB6D7
0329:0381 N,S	TRBP
0330:	0385 N [TB9A6],TB9A5
0331:	HODF C TB8D4.-0385
0332:	HODS C TB8D7.-0385.-0383
0333:0382 N,S	TRBP
0334:	0378 N [TB9B6],TB9B5
0335:	0389 N [TB9B4],TB9B2
0336:	0391 N [TB9B4],TB9B3

0337:	COUT N [TB9B4],TB10A8
0338:	HODF C TB9B3
0339:	HODS C TB9B2.-0383
0340:0383 N,S	TRBP
0341:	0389 N [TB11B20],TB11B19
0342:	HODS C
0343:0384 N,S	TRBP
0344:	0380 N [TB6D7],TB6D6
0345:0385 N,S	TRBP
0346:	0389 N [TB9A9],TB9A1
0347:	0391 N [TB9A9],TB8D5
0348:	HODF C TB8D5
0349:	HODS C TB9A1.-0383
0350:0389 N,S	TRBP
0351:	0382 N [TB11C3],TB11C2
0352:	0384 N [TB11C3],TB11C1
0353:	0393 N [TB11C5],TB11C4
0354:	H389 C
0355:0390 N,S	TRBP
0356:	0382 N [TB6D5],TB6D4
0357:	0384 N [TB6D5],TB6D3
0358:0391 N,S	TRBP
0359:	0382 N [TB9A12],TB9A11
0360:	0384 N [TB9A12],TB9A10
0361:	0395 N [TB9A14],TB9A13
0362:	H391 C
0363:0392 N,S	TRBP

0364:	0390 N [TB6C20],TB6C19
0365:0393 N,S	TRBP
0366:	0397 N [TB9A16],TB11C6
0367:0394 N,S	TRBP
0368:	0392 N [TB6C19],TB6C18
0369:0395 N,S	TRBP
0370:	0397 N [TB9A16],TB9A15
0371:0396 N,S	TRBP
0372:	0394 N [TB6C18],TB6C17
0373:0397 N,S	TRBP
0374:	0399 N [TB6A1],TB9A19
0375:0398 N,S	TRBP
0376:	0396 N [TB6C17],TB6C16
0377:	H398 C
0378:0399 N,S	TRBP
0379:	0401 N [T7015/6/2],TB6A1
0380:0401 N,S	TRBP
0381:	0403 N [T7111],T7015/6/2
0382:0402 N,S	TRBP
0383:	0398 N [TB6C16],TB6C15
0384:	HOUF C
0385:0403 N,S	TRBP
0386:	0409 N [T7211],T7111
0387:0404 N,S	TRBP
0388:	0402 N [TB6C15],T7221
0389:	HOUF C TB6C3.-0402
0390:0409 N,S	TRBP

0391: 0413 N [T7312],T7211

0392: DFAP C TB6B10.477(2)M.435(1)M.423(3)M.
417(2)M.-T7312.-T7411.-T7714.
-T7814.-0413.-0417.-0423.-0435.
-0473.-0477.-0487.-0493

0393:0413 N,S TRBP

0394: 0417 N [T7411],T7312

0395: DFAP C TB6B10.477(2)M.435(1)M.423(3)M.
417(2)M.-T7411.-T7714.-T7814.
-0417.-0423.-0435.-0473.-0477.
-0487.-0493

0396:0417 N,S TRBP

0397: 0421 N [T7413],417(1)M

0398: 0423 N [T7413],417(2)M

0399: DFAP C TB6B10.417(2)M.477(2)M.435(1)M.
423(3)M.-T7714.-T7814.-0423.
-0435.-0473.-0477.-0487.-0493

0400:0418 N,S TRBP

0401: 0404 N [T7221],T7322

0402: HOUF C -T7221.-0404.-0402

0403:0421 N,S TRBP

0404: 0442 N [T7505],(421(2)M+421(2)C+
421(2)W).0449

0405: 0443 N [T7505],(421(1)M+421(1)C).
-0443

0406: 0444 N [T7505],(421(1)M+421(1)C).
0443

0407: 0449 N [T7505],[421(2)M+421(2)C+
421(2)W).-0449

0408: COUT N [T7405],S56.R1194

0409: COUT N [T7501],S56.R1194

0410:0422 N,S TRBP

0411: 0418 N [T7322],T7421

0412: HOUF C -T7221.-T7322.-0418.-0404.-0402

0413:0423 N,S TRBP

0414: 0435 N [T7515],423(3)M

0415: 0436 N [T7515],[423(5)M+423(5)C).0437

0416: 0437 N [T7515],[423(5)M+423(5)C).-0437

0417: 0438 N [T7515],[423(4)M+423(4)C).0445

0418: 0442 N [T7515],[423(2)M+423(2)C+
423(2)W).0449

0419: 0443 N [T7515],[423(1)M+423(1)C).
-0443

0420: 0444 N [T7515],[423(1)M+423(1)C).
0443

0421: 0445 N [T7515],[423(4)M+423(4)C).-0445

0422: 0449 N [T7515],[423(2)M+423(2)C+
423(2)W).-0449

0423: DFAP C TB6B10.423(3)M.435(1)M.477(2)M
.T7714.-T7814.-0435.-0473.
-0477.-0487.-0493

0424:0426 N,S TRBP

0425: 0422 N [T7421],T7423

0426: HOUF C -T7221.-T7322.-T7421.-0422.

-0418.-0404.-0402

0427:0428 N,S	TRBP
0428:	0426 N [T7532],428(1)M
0429:0430 N,S	TRBP
0430:	0426 N [T7522],430(1)M
0431:	0436 N [T7525],63(3)S.0437
0432:	0437 N [T7525],63(3)S.-0437
0433:	0438 N [T7525],63(2)S.0445
0434:	0445 N [T7525],63(2)S.-0445
0435:0431 N	TRBP
0436:	0448 N 0431.-0448.T0812. (S448+76(2)S+462(2)C+470(2)C)
0437:	0471 N [T0813],431(1)M
0438:	COUT N [T0813],431(2)S
0439:0433 N	TRBP
0440:	0446 N 0433.-0446.T0822. (S446+78(7)S+76(3)S+462(3)C+ 458(10)C+466(10)C+468(8)C+ 470(3)C+470(4)C)
0441:	0471 N [T0823],433(1)M
0442:	0473 N [T0823],433(2)M
0443:	0469 N [T0823],433(3)M
0444:	COUT N [T0823],433(4)S
0445:	0458 N [T0823],433(5)S
0446:0434 N	TRBP
0447:	7980 N [T0830],434(1)M
0448:0435 N,S	TRBP

0449: 0458 N [T7612],435(3)S
0450: 0473 N [T7612],435(1)M
0451: DFAP C TB6B10.435(1)M.477(2)M.-T7814.
-T7714.-0473.-0477.-0487.-0493
0452:0436 N,S TRBP
0453: 0437 N 0436.-0437.T7631.
(S437+63(3)S+423(5)C)
0454: 0423 N [T7630],436(3)S
0455: 0428 N [T7630],436(2)M
0456: 0430 N [T7630],436(1)M
0457:0437 N,S TRBP
0458: 0436 N 0437.-0436.T7631.
(S436+74(1)S+66(1)S+78(6)S+
468(5)C+466(5)C+466(6)C+
458(5)C+458(6)C)
0459: 0458 N [T7632],437(2)S+(437(3)S.
77(2)S)
0460: 0469 N [T7632],437(5)M
0461: 0473 N [T7632],437(1)M
0462: COUT N [T7632],(437(3)S+437(4)S).-S77
0463:0438 N,S TRBP
0464: 0445 N 0438.-0445.T7638.(S445+423(4)C+
63(2)S)
0465: 0423 N [T7637],438(2)S
0466: 0430 N [T7637],438(1)M
0467:0440 N,S TRBP
0468: 0423 N [T7621],440(2)S

0469: 0430 N [T7621],440(1)M

0470:0442 N,S TRBP

0471: 0449 N 0442.-0449.T7643.(S449+423(2)C+
423(2)W+421(2)W+
421(2)C+799(3)C+799(3)W+65(2)S)

0472: 0434 N [T7601],442(1)M

0473: 0421 N [T7601],442(2)M

0474: 0423 N [T7601],442(4)S

0475: COUT N [T7601],442(3)S

0476:0443 N,S TRBP

0477: 0444 N 0443.-0444.T7603.
(S444+462(4)C+76(4)S+78(1)S+
458(1)C+466(1)C+468(1)C+
470(5)C+470(6)C)

0478: 0458 N [T7604],443(4)S

0479: 0469 N [T7604],443(3)M

0480: 0471 N [T7604],443(1)M

0481: 0473 N [T7604],443(2)M

0482: COUT N [T7604],443(5)S

0483:0444 N,S TRBP

0484: 0443 N 0444.-0443.T7603.(S443+421(1)C+
423(1)C+799(2)C+65(1)S)

0485: 0421 N [T7602],444(2)M

0486: 0423 N [T7602],444(4)S

0487: 0434 N [T7602],444(1)M

0488: COUT N [T7602],444(3)S

0489:0445 N,S TRBP

0490: 0438 N 0445.-0438.T7638.(S438+78(5)S+
458(4)C+466(4)C+468(4)C)

0491: 0458 N [T7639],445(3)S

0492: 0469 N [T7639],445(2)M

0493: 0473 N [T7639],445(1)M

0494:0446 N TRBP

0495: 0433 N 0446.-0433.T0822.
(S433+797(3)C+799(1)C)

0496: 7960 N [T0821],446(1)M

0497: 7980 N [T0821],446(2)M

0498:0448 N TRBP

0499: 0431 N 0448.-0431.T0812.
(S431+797(2)C)

0500: 7960 N [T0811],448(1)M

0501:0449 N,S TRBP

0502: 0442 N 0449.-0442.T7643.(S442+470(7)C+
468(2)C+466(2)C+458(2)C+78(2)S+
76(5)S)

0503: 0458 N [T7646],449(4)S

0504: 0471 N [T7646],449(1)M

0505: 0473 N [T7646],449(2)M

0506:0451 N TRBP

0507: 0800 N 0451.-0800.(T0801+T0802+T0803).
(S800+76(1)S+462(1)C+470(1)C)

0508: 0471 N [T0804],451(1)M

0509: COUT N [T0804],451(2)S

0510:0458 N,S TRCP

0511: 0436 N [T7731],-0436.((458(5)M+458(5)C
+458(6)M+458(6)C)+(458(9)S.
S74))

0512: 0437 N [T7731],0436.((458(5)M+458(5)C+
458(6)M+458(6)C)+(458(9)S.S74))

0513: 0438 N [T7731],(458(4)M+458(4)C).-0438

0514: 0440 N [T7731],458(3)M

0515: 0442 N [T7731],(458(2)M+458(2)C).-0442

0516: 0443 N [T7731],(458(1)M+458(1)C).0444

0517: 0444 N [T7731],(458(1)M+458(1)C).-0444

0518: 0445 N [T7731],(458(4)M+458(4)C).0438

0519: 0446 N [T7731],(458(10)M+458(10)C).-0446

0520: 0433 N [T7731],(458(10)M+458(10)C).0446

0521: 0449 N [T7731],(458(2)M+458(2)C).0442

0522: COUT N [T7731],458(9)S.-S74

0523: COUT N [T7752],S79

0524:0462 N TRBP

0525: 0800 N [T7607],462(1)M+462(1)C.-0800

0526: 0451 N [T7607],462(1)M+462(1)C.0800

0527: 0448 N [T7607],462(2)M+462(2)C.-0448

0528: 0431 N [T7607],462(2)M+462(2)C.0448

0529: 0446 N [T7607],462(3)M+462(3)C.-0446

0530: 0433 N [T7607],462(3)M+462(3)C.0446

0531: 0444 N [T7607],462(4)M+462(4)C.-0444

0532: 0443 N [T7607],462(4)M+462(4)C.0444

0533:0466 D[0469],S TRCP

0534: 0433 N [T7732],(466(10)M+466(10)C).0446

0535: 0436 N [T7732],-0436.((466(5)M+466(5)C
+466(6)M+466(6)C)+(466(9)S.
S74))

0536: 0437 N [T7732],0436.((466(5)M+466(5)C+
466(6)M+466(6)C)+(466(9)S.S74))

0537: 0438 N [T7732],(466(4)M+466(4)C).-0438

0538: 0440 N [T7732],466(3)M

0539: 0442 N [T7732],(466(2)M+466(2)C).-0442

0540: 0443 N [T7732],(466(1)M+466(1)C).0444

0541: 0444 N [T7732],(466(1)M+466(1)C).-0444

0542: 0445 N [T7732],(466(4)M+466(4)C).0438

0543: 0446 N [T7732],(466(10)M+466(10)C).-0446

0544: 0449 N [T7732],(466(2)M+466(2)C).0442

0545: COUT N [T7732],466(9)S.-S74

0546:0468 N,S TRCP

0547: 0433 N [T7722],(468(8)M+468(8)C).0446

0548: 0436 N [T7722],(468(5)M+468(5)C).-0436

0549: 0437 N [T7722],(468(5)M+468(5)C).0436

0550: 0438 N [T7722],(468(4)M+468(4)C).-0438

0551: 0440 N [T7722],468(3)M

0552: 0442 N [T7722],(468(2)M+468(2)C).-0442

0553: 0443 N [T7722],(468(1)M+468(1)C).0444

0554: 0444 N [T7722],(468(1)M+468(1)C).-0444

0555: 0445 N [T7722],(468(4)M+468(4)C).0438

0556: 0446 N [T7722],(468(8)M+468(8)C).-0446

0557: 0449 N [T7722],(468(2)M+468(2)C).0442

0558:0469 D[0466],S TRCP

0559: 0483 N [T7734],T7733

0560: DFAP C TB6B10.483(2)M.-T7814.-0483.-
0487.-0493

0561:0470 N TRCP

0562: 0451 N [T7742],(470(1)M+470(1)C).0800

0563: 0431 N [T7742], (470(2)M+470(2)C).0448

0564: 0433 N [T7742], (470(3)M+470(3)C+470(4)M+470(4)C).0446

0565: 0442 N [T7742],(470(7)M+470(7)C).-0442

0566: 0443 N [T7742], (470(5)M+470(5)C+470(6)M+470(6)C).0444

0567: 0444 N [T7742],(470(5)M+470(5)C+470(6)M+470(6)C).-0444

0568: 0446 N [T7742], (470(3)M+470(3)C+470(4)M+470(4)C).-0446

0569: 0448 N [T7742], (470(2)M+470(2)C).-0448

0570: 0449 N [T7742],(470(7)M+470(7)C).0442

0571: 0800 N [T7742],(470(1)M+470(1)C).-0800

0572:0471 N TRCP

0573: 0451 N [T7609],76(1)S.0800

0574: 0431 N [T7609],76(2)S.0448

0575: 0433 N [T7609],76(3)S.0446

0576: 0442 N [T7609],76(5)S.-0442

0577: 0443 N [T7609],76(4)S.0444

0578: 0444 N [T7609],76(4)S.-0444

0579: 0446 N [T7609],76(3)S.-0446

0580: 0448 N [T7609],76(2)S.-0448

0581: 0449 N [T7609],76(5)S.0442

0582: 0475 N [T7702],T7701

0583: 0800 N [T7609],76(1)S

0584: DSAP C 475(1)M.-T7703.-0475.-0485

0585:0472 N	TRCP
0586:	0466 N [T7734],T7735
0587:0473 N,S	TRCP
0588:	0433 N [T7614],78(7)S.0446
0589:	0436 N [T7614],78(6)S.-0436
0590:	0437 N [T7614],78(6)S.0436
0591:	0438 N [T7614],78(5)S.-0438
0592:	0440 N [T7614],78(4)S
0593:	0442 N [T7614],78(2)S.-0442
0594:	0443 N [T7614],78(1)S.0444
0595:	0444 N [T7614],78(1)S.-0444
0596:	0445 N [T7614],78(5)S.0438
0597:	0446 N [T7614],78(7)S.-0446
0598:	0449 N [T7614],78(2)S.0442
0599:	0477 N [T7713],T7712
0600:	DFAP C TB6B10.477(2)M.-T7714.-T7814. -0477.-0487.-0493
0601:0474 N	TRCP
0602:	0468 N [T7724],T7725
0603:0475 N	TRCP
0604:	0485 N [T7705],475(1)M
0605:	DSAP C 475(1)M.-0485
0606:0476 N	TRCP
0607:	0470 N [T7744],T7745
0608:0477 N	TRCP
0609:	0485 N [T7715],477(1)M
0610:	0487 N [T7715],477(2)M

0611: DFAP C TB6B10.477(2)M.-T7814.-0487.
-0493

0612: DSAP C 477(1)M.-0485

0613:0479 N TRCP

0614: 0485 N [T7851],479(1)M

0615: 0487 N [T7851],479(2)M

0616: 0489 N [T7851],479(3)M

0617: COUT N [-T7851],T7756

0618: DSAP C 479(1)M.-0485

0619:0481 N TRCP

0620: 0485 N [T7851],481(1)M

0621: 0487 N [T7851],481(2)M

0622: 0489 N [T7851],481(3)M

0623: COUT N [-T7851],T7765

0624: DSAP C 481(1)M.-0485

0625:0483 N TRCP

0626: 0485 N [T7735],483(1)M

0627: 0487 N [T7735],483(2)M

0628: 0489 N [T7735],483(3)M

0629: DSAP C 483(1)M.-0485

0630: DFAP C TB6B10.483(2)M.-T7814.-0487
.-0493

0631:0484 D[0489] TRCP

0632: 0472 N [T7831],484(1)M

0633: 0481 N [T7831],484(3)S+484(4)S

0634: COUT N [T7831],484(2)S

0635:0485 N TRCP

0636: T TRAH DSAP
0637: 0472 N [T7705],92(3)S
0638: 0474 N [T7705],92(2)S
0639: 0476 N [T7705],92(1)S
0640: 0481 N [T7705],92(5)S+92(6)S
0641: 0491 N [TB2C3],T7802
0642: COUT N [T7705],92(4)S
0643: DSAP C
0644:0486 N TRCP
0645: 0472 N [T7821],486(2)M
0646: 0474 N [T7821],486(1)M
0647: 0481 N [T7821],486(4)S+486(5)S
0648: COUT N [T7821],486(3)S
0649:0487 N TRCP
0650: T TRAJ P487 TB6C10.-0493
0651: 0472 N [T7716],90(2)S
0652: 0474 N [T7716],90(1)S
0653: 0479 N [T7716],90(3)S
0654: 0481 N [T7716],90(5)S+90(6)S
0655: 0493 N [T7814],T7812
0656: COUT N [T7716],90(4)S
0657: DFAP C TB6B10.-T7814.-0493
0658:0488 N TRCP
0659: 0472 N [T7841],488(3)M
0660: 0474 N [T7841],488(2)M
0661: 0476 N [T7841],488(1)M
0662: 0481 N [T7841],488(5)S+488(6)S

0663: COUT N [T7841],488(4)S
0664:0489 D[0484] TRCP
0665: T TRAJ P489
0666: 0495 N [T7833],T7832
0667:0491 N TRCP
0668: T TRAH P491
0669: 0501 N [TB12B8],TB2C3
0670:0492 D[0495] TRCP
0671: 0484 N [T7833],TB1B17
0672:0493 N TRCP
0673: T TRAJ P493 TB6C10
0674: T TRAH DFAP TB6B10
0675: 0503 N [TB3A18],TB3A15
0676: SD28 N [TB3A18],TB3A16
0677: DFAP C TB6B10
0678:0494 N TRCP
0679: 0486 N [T7823],TB1B15
0680:0495 D[0492] TRCP
0681: T TRAJ P495
0682: SD28 N [T7930],495(1)M
0683:0496 N TRCP
0684: 0488 N [T7843],T7844
0685:0500 N TRCP
0686: 0492 N [TB1B9],TB1B8
0687: 0494 N [TB1B9],TB1B7
0688:0501 N TRCP
0689: T TRAH P501

0690:	0505 N [TB12B9],TB12B8
0691:0502 N	TRCP
0692:	0494 N [TB1B6],TB1B5
0693:0503 N	TRCP
0694: T	TRAH P503
0695:	0507 N [T8011],TB3A19
0696:0504 N	TRCP
0697:	0496 N [T7942/3],TB1B3
0698:0505 N	TRCP
0699: T	TRAH P505
0700:	0511 N [TB12B10],TB12B9
0701:0506 N	TRCP
0702:	0500 N [TB1A16],TB1A14
0703:0507 N	TRCP
0704: T	TRAH P507
0705:	0513 N [TB11C13],TB3A20
0706:0508 N	TRCP
0707:	0502 N [TB1A8],TB1A6
0708:0510 N	TRCP
0709:	0504 N [TB1B3],TB1B1
0710:0511 N	TRCP
0711: T	TRAU P511 TB12B13
0712:	0521 N [TB12B15],TB12B12
0713:	0801 N [TB12B15],TB12B13
0714:0512 N	TRCP
0715:	0506 N [TB1A14],TB1A12
0716:0513 N	TRCP

0717:	0523 N [TB11C14],TB11C13
0718:0514 N	TRCP
0719:	0508 N [TB1A6],TB1A4
0720:0516 N	TRCP
0721:	0510 N [TB1B1],TB1A20
0722:0521 N	TRCP
0723:	0531 N [TB12B20],TB12B19
0724:0523 N	TRCP
0725:	0533 N [TB11C15],TB11C14
0726:0524 N	TRCP
0727:	0512 N [TB1A12],TB1A10
0728:0526 N	TRCP
0729:	0514 N [TB1A4],TB1A2
0730:0531 N	TRCP
0731:	0535 N [TB12C1],TB12B20
0732:0532 N	TRCP
0733:	0524 N [TB1A10],TB1A9
0734:0533 N	TRCP
0735:	0537 N [TB11C16],TB11C15
0736:0534 N	TRCP
0737:	0526 N [TB1A2],TB1A1
0738:0535 N	TRCP
0739:	0541 N [TB12C3],TB12C2
0740:0536 N	TRCP
0741:	0532 N [TB1A9],TB14A15
0742:	0542 N [TB14A16],TB14A14
0743:0537 N	TRCP

0744:	0543 N [TB11C17],TB11C16
0745:0538 N	TRCP
0746:	0534 N [TB1A1],TB13C5
0747:0541 N	TRCP
0748:	0542 N [TB12C7],TB12C6
0749:	0545 N [TB12C7],TB12C4
0750:	0547 N [TB12C7],TB12C5
0751:0542 N	TRCP
0752:	0536 N [TB14A11],TB14A7
0753:	0538 N [TB14A11],TB14A8
0754:	0541 N [TB14A11],TB14A10
0755:	COUT N [TB14A11],TB14A9
0756:0543 N	TRCP
0757:	0542 N [TB11D1],TB11C20
0758:	0545 N [TB11D1],TB11C19
0759:	0547 N [TB11D1],TB11C18
0760:0544 N	TRCP
0761:	0536 N [TB13C4],TB13C3
0762:	0538 N [TB13C4],TB13C2
0763:0545 N	TRCP
0764:	0549 N [TB12C9],TB12C8
0765:0546 N	TRCP
0766:	0542 N [TB14A6],TB14A5
0767:0547 N	TRCP
0768:	0551 N [TB11D3],TB11D2
0769:0548 N	TRCP
0770:	0544 N [TB13B10],TB13B9

0771:0549 N	TRCP
0772:	0553 N [TB12C10],TB12C9
0773:0551 N	TRCP
0774:	0555 N [TB11D4],TB11D3
0775:0552 N	TRCP
0776: T	TRAH P552
0777:	0546 N [TB13D6],TB13D5
0778:0553 N	TRCP
0779:	0557 N [TB12C12],TB12C10
0780:0554 N	TRCP
0781: T	TRAH P554
0782:	0548 N [TB13B9],TB13B8
0783:0555 N	TRCP
0784:	0559 N [TB11D5],TB11D4
0785:0556 N	TRCP
0786: T	TRAH P556
0787:	0552 N [TB13D5],TB13D4
0788:0557 N	TRCP
0789:	0561 N [TB12C13],TB12C12
0790:0558 N	TRCP
0791: T	TRAH P558
0792:	0554 N [TB13B8],TB13B7
0793:0559 N	TRCP
0794:	0563 N [TB11D6],TB11D5
0795:0561 N	TRCP
0796:	0565 N [TB12C14],TB12C13
0797:0563 N	TRCP

0798:	0567 N [TB11D7],TB11D6
0799:0564 N	TRCP
0800: T	TRAH USAP TB14A1
0801:	0556 N [TB13D4],TB13D3
0802:	USAP C TB14A1
0803:0565 N	TRCP
0804:	0569 N [TB12C15],TB12C14
0805:0566 N	TRCP
0806: T	TRAH UFAP TB13B15
0807:	0558 N [TB13B7],TB13B6
0808:	UFAP C TB13B15
0809:0567 N	TRCP
0810:	0571 N [TB12A1],TB11D7
0811:0568 N	TRCP
0812:	0564 N [TB13D3],TB13D2
0813:	USAP C TB13D7.-0564
0814:0569 N	TRCP
0815:	0573 N [TB12C16],TB12C15
0816:0570 N	TRCP
0817:	0566 N [TB13B6],TB13B5
0818:	UFAP C TB13B13.-0566
0819:0571 N	TRCP
0820:	0575 N [TB12A2],TB12A1
0821:0572 N	TRCP
0822:	0568 N [TB13D2],TB13D1
0823:0573 N	TRCP
0824:	0577 N [TB12C18],TB12C16

0825:0574 N	TRCP
0826:	0570 N [TB13B5],TB13B4
0827:	UFAP C TB13B12.-0566.-0570
0828:0575 N	TRCP
0829:	0579 N [TB12A3],TB12A2
0830:0576 N	TRCP
0831:	0572 N [TB13D1],TB13C17
0832:0577 N	TRCP
0833:	0581 N [TB12D2],TB12C19
0834:0578 N	TRCP
0835:	0574 N [TB13B4],TB13A20
0836:	UFAP C TB13B11.TB13B12.-0566.-0570. -0574
0837:0579 N	TRCP
0838:	0583 N [TB12A6],TB12A5
0839:0580 N	TRCP
0840:	0576 N [TB13C17],TB13C16
0841:0581 N	TRCP
0842:	0585 N [TB12D3],TB12D2
0843:0582 N	TRCP
0844:	0578 N [TB13A20],TB13A19
0845:	UFAP C TB13B11.TB13B12.-TB13A20.- 0566.-0570.-0574.-0578
0846:0583 N	TRCP
0847:	0587 N [TB12A8],TB12A6
0848:0584 N	TRCP
0849:	0580 N [TB13C16],TB13C15

0850:0585 N	TRCP
0851:	0589 N [TB12D4],TB12D3
0852:0586 N	TRCP
0853:	0582 N [TB13A19],TB13A18
0854:0587 N	TRCP
0855:	0591 N [TB12A9],TB12A8
0856:	D001 C TB12A18.-0591.-0595.-0599. -0603.-0607.-0611.-0615.-0617
0857:0589 N	TRCP
0858:	0593 N [TB12D5],TB12D4
0859:0591 N	TRCP
0860:	0595 N [TB12A10],TB12A9
0861:	D001 C TB12A19.-0595.-0599.-0603.-0607. -0611.-0615.-0617
0862:0592 N	TRCP
0863:	0584 N [TB13C15],TB13C14
0864:0593 N	TRCP
0865:	0597 N [TB12D6],TB12D5
0866:0594 N	TRCP
0867:	0586 N [TB13A18],TB13A16
0868:0595 N	TRCP
0869:	0599 N [TB12A11],TB12A10
0870:	D001 C TB12A20.-0599.-0603.-0607. -0611.-0615.-0617
0871:0596 N	TRCP
0872:	0592 N [TB13C14],TB13C13
0873:0597 N	TRCP

0874: 0601 N [TB12D7],TB12D6

0875:0598 N TRCP

0876: 0594 N [TB13A16],TB13A15

0877:0599 N TRCP

0878: 0603 N [TB12A12],TB12A11

0879: D001 C TB12B1.-0603.-0607.-0611.-0615.
-0617

0880:0600 N TRCP

0881: 0596 N [TB13C13],TB13C12

0882:0601 N TRCP

0883: 0605 N [TB13A1],TB12D7

0884: D001 C TB13A3.-0605.-0609.-0613.-0617

0885:0602 N TRCP

0886: 0598 N [TB13A15],TB13A14

0887:0603 N TRCP

0888: 0607 N [TB12A13],TB12A12

0889: D001 C TB12B2.-0607.-0611.-0615.-0617

0890:0604 N TRCP

0891: 0600 N [TB13C12],TB13C10

0892:0605 N TRCP

0893: 0609 N [TB13A2],TB13A1

0894: D001 C TB13A4.-0609.-0613.-0617

0895:0606 N TRCP

0896: 0602 N [TB13A14],TB13A13

0897:0607 N TRCP

0898: 0611 N [TB12A14],TB12A13

0899: D001 C TB12B3.-0611.-0615.-0617

0900:0608 N	TRCP
0901:	0604 N [TB13C10],TB13C9
0902:0609 N	TRCP
0903:	0613 N [TB13A7],TB13A2
0904:	D001 C TB13A5.-0613.-0617
0905:0610 N	TRCP
0906:	0606 N [TB13A13],TB13A12
0907:0611 N	TRCP
0908:	0615 N [TB12A15],TB12A14
0909:	D001 C TB12B4.-0615.-0617
0910:0612 N	TRCP
0911: R	TRAD 9112
0912:	0608 N [TB13A11],TB13A10
0913:	0610 N [TB13A11],TB13A9
0914:0613 N	TRCP
0915:	0617 N [TB13A8],TB13A6
0916:	D001 C TB13A6.-0617
0917:0615 N	TRCP
0918:	0617 N [TB12B6],TB12B5
0919:	D001 C TB12B5.-0617
0920:0617 N,JK	TRCP
0921:	COUT N [-TB12B7]
0922:	D001 C
0923:0769 N,DJKU	TRBP
0924: R	TRAX 9769
0925:	0773 N [TB10A15],TB10A14
0926:0771 N,DJKU	TRBP

0927: R TRAX 9771
0928: 0775 N [TB8A7],TB8A6
0929: EVDF C TB8A10.-0775.-0263.-0269.-0273.
-0277
0930:0773 N,JK TRBP
0931: 0261 N [TB10A16],TB10A15
0932:0775 N,JK TRBP
0933: 0263 N [TB8A8],TB8A7
0934: EVDF C TB8A11.-0263.-0269.-0273.-0277
0935:0781 N,DU TRBP
0936: T TRAE PBAP
0937: R TRAE
0938: 0783 N [T9753]
0939:0783 N TRBP
0940: 0785 N [T9851],T9753
0941:0785 N TRBP
0942: 0793 N [T9953],T9851
0943:K786 N,JK TRBP
0944: T TRAE 0786
0945: COUT N [-T9962],T9861
0946:0793 N TRBP
0947: 0797 N [T9954],793(1)M
0948: 0799 N [T9954],793(2)M
0949:0794 N TRBP
0950: T TRAE P794
0951: K786 N [T9962],T9963
0952:7960 D[0797] TRBP

0953: 0794 N [T9955],796(1)M
0954:0796 N,JKS TRBP
0955: 0266 N [TB8A3],TB7D5
0956: 0268 N [TB8A3],TB7D4
0957: 0271 N [TB8A3],TB8A1
0958: 0273 N [TB8A3],TB7D7
0959: CLRT N [TB8A3],TB7D6
0960: CLRT N [-TB8A5]
0961: KXUF C
0962:0797 D[7960] TRBP
0963: 0451 N [T9957],(797(1)M+797(1)C).-0451
0964: 0800 N [T9957],(797(1)M+797(1)C).0451
0965: 0431 N [T9957],(797(2)M+797(2)C).-0431
0966: 0448 N [T9957],(797(2)M+797(2)C).0431
0967: 0433 N [T9957],(797(3)M+797(3)C).-0433
0968: 0446 N [T9957],(797(3)M+797(3)C).0433
0969:7980 D[0799] TRBP
0970: 0794 N [T9965],798(1)M
0971:0798 N,JKS TRBP
0972: 0266 N [TB10A11],TB10A13
0973: CLRT N [TB10A11],TB10A12
0974: CLRT N [-TB10A10]
0975: KXUS C
0976:0799 D[7980] TRBP
0977: 0433 N [T9967],(799(1)M+799(1)C).-0433
0978: 0446 N [T9967],(799(1)M+799(1)C).0433
0979: 0443 N [T9967],(799(2)M+799(2)C).-0443

0980: 0444 N [T9967],[799(2)M+799(2)C].0443

0981: 0449 N [T9967],[799(3)M+799(3)W+799(3)C].-0449

0982: 0442 N [T9967],[799(3)M+799(3)W+799(3)C].0449

0983:0800 N TRBP

0984: 0451 N 0800.-0451.(T0801+T0802+T0803).
(S451+797(1)C)

0985: 7960 N [T7691],800(1)M

0986:0801 N TRCP

0987: T TRAU P801

0988: UB05 N [TB12B17],TB12B16

0989:0802 N TRCP

0990: T TRAU P802

0991: T TRAH P802

0992: 0516 N [TB1A19],TB1A18

0993:0804 N,DJKU TRCP

0994: R TRAU

0995: T TRAH P804

0996:0862 N TRCP

0997: T TRAJ P862

0998: 0492 N [TB1B11],TB1B10

0999:0864 N,DJKU TRCP

1000: R TRAJ

*

*PETERBOROUGH CCTV PANEL BERTHS

*

1001:E279 N,JKPZ TREP

1002:E281 N,JKPZ TREP

1003:E282 N,JKPZ	TREP
1004:E284 N,JKPZ	TREP
1005:EVDF N,DJKPZ	TREP
1006:EVDS N,DJKPZ	TREP
1007:EVUF N,DJKPZ	TREP
1008:EVUS N,DJKPZ	TREP
1009:F329 N,JKPZ	TREP
1010:F330 N,JKPZ	TREP
1011:F331 N,JKPZ	TREP
1012:F332 N,JKPZ	TREP
1013:FFDF N,DJKPZ	TREP
1014:FFUF N,DJKPZ	TREP
1015:	COUT N [-0344],FFUF.-0340.-0336
1016:FFDS N,DJKPZ	TREP
1017:FFUS N,DJKPZ	TREP
1018:	COUT N [-0344],FFUS.-0338.-0334
1019:H389 N,JKPZ	TREP
1020:H391 N,JKPZ	TREP
1021:H398 N,JKPZ	TREP
1022:HODF N,DJKPZ	TREP
1023:HODS N,DJKPZ	TREP
1024:HOUF N,DJKPZ	TREP
*	
* TD SUPPORT BERTHS	
*	
1025:DUMY N,BHJKP	
1026:	COUT N [U7606-AB]

1027: COUT N [U7765-AB]

1028:COUT Z

1029: TRAD

1030: TRAX

1031: TRAE

1032: TRAJ

1033: TRAU

1034: TRAH

1035:STIN Y

1036: TRAD

1037: TRAX

1038: TRAE

1039: TRAJ

1040: TRAU

1041: TRAH

1042:CLCK C RAD1

1043: TRBP

1044: TRCP

1045: TRDP

1046:YEAR G TRBP RAD1

1047: TRCP

1048: TRDP

1049:DATE F TRBP RAD1

1050: TRCP

1051: TRDP

1052:TEST N,BHPZ

1053:CLRT N,JKPVZS

*

* NON DESCRIBED ALARM STEPS

*

1054:NDCN N,JKPVZ

1055: 0313 N [TB10D1],-0313
1056: 0267 N [TB10B6],-0267
1057: 0271 N [TB10B13],-0271
1058: 0305 N [TB10C5],TB10C4.-0305
1059: 0304 N [-TB10A1],-0304
1060: 0306 N [-TB10D3],-0306
1061: 0308 N [TB10C14],-0308
1062: 0347 N [-TB11A18],-0347
1063: 0348 N [TB9A8],-0348
1064: 0353 N [TB11B6],-0353
1065: 0351 N [TB11B5],-0351
1066: 0382 N [TB9A20],-0382
1067: 0421 N [T7405],-S56.R1194
1068: 0436 N [T7632],S66.-T7631
1069: 0436 N [T7633],S74.-T7631
1070: 0437 N [T7632],S66.T7631
1071: 0437 N [T7633],S74.T7631
1072: 0442 N [T9969],S65.65(2)S.T7643
1073: 0443 N [T9969],S65.65(1)S.-T7603
1074: 0444 N [T9969],S65.65(1)S.T7603
1075: 0449 N [T9969],S65.65(2)S.-T7643
1076: 0458 N [S458],T7752
1077: 0458 N [T7752],S458

1078: 0479 N [S479],T7756
1079: 0479 N [T7756],S479
1080: 0481 N [S481]
1081: 0485 N [S89],89(1)S.T7757
1082: 0485 N [T7757],S89.89(1)S
1083: 0487 N [S89],89(2)S.T7757
1084: 0487 N [T7757],S89.89(2)S
1085: 0536 N [TB14A15],TB14A13.-0536
1086: 0542 N [TB14A12],-0542
1087: 0796 N [TB8A4],-0796
1088: 0798 N [TB8A2],-0798

*

* ST JAMES DEEPING SUPPORT BERTHS

*

1089:SD26 N,JKV

1090: T TRAJ 0026

1091: R TRAJ

1092:SD28 N,JK

1093: T TRAJ 0028

1094: SD26 N [TB3B2],TB3B1

*

* UFFINGTON & BARNACK SUPPORT BERTHS

*

1095:UB05 N,JKPVZ

1096: T TRAU 0005

1097: R TRAU

*

* HELPSTON SUPPORT BERTHS

*

1098:DFAP N,JKPVZ

1099: T TRAH

1100:DSAP N,JKPVZ

1101: T TRAH

1102:UFAP N,JKPVZ

1103: T TRAH

1104:USAP N,JKPVZ

1105: T TRAH

*

* DONCASTER SUPPORT BERTHS

*

1106:D001 N,JKPVZ

1107: T TRAD 0930

1108:0618 N,DJKU TRCP

1109: R TRAD 9008

1110:0620 N,DJKU TRCP

1111: R TRAD 9010

1112:0614 N,DJKU TRCP

1113: R TRAD 9614

*

* KINGS CROSS SUPPORT BERTHS

*

1114:KXUF N,JKPVZ

1115: T TRAX 0796

1116:KXUS N,JKPVZ

1117: T TRAX 0798

*

* LINK / EMERGENCY ALARM BERTHS AND THE CLOCK BERTH

* SMART TO GET ALARM BERTHS TOO

*

1118:DN01 A,JKP TRCP

1119:DN02 A,JKP TRCP

1120:TRAD A,JKP TRCP

1121:KX01 A,JKP TRBP

1122:KX02 A,JKP TRBP

1123:TRAX A,JKP TRBP

1124:CA01 A,JKP TRDP

1125:TRAJ A,JKP TRCP

1126:TRAE A,JKP TRBP

1127:TRAH A,JKP TRCP

1128:TRAU A,JKP TRCP

1129:TRZP A,JKP TRDP

1130:TRBP A,JKP TRDP

1131:TRCP A,JKP TRDP

1132:TRDP A,JKP TRBP

1133:TREP A,JKP TRDP

1134:SSIF A,JKP TRDP

1135:I01A A,JKP TRDP

1136:I01B A,JKP TRDP

1137:I02A A,JKP TRDP

1138:I02B A,JKP TRDP

1139:I03A A,JKP TRDP
1140:I03B A,JKP TRDP
1141:TDTT A,JKP
1142:IPTT A,JKP
1143:UDLL A,JKP
1144:IPLK A,JKP
1145:RADL A,JKP TRDP
1146:TLOG A,JKP TRDP
1147:TRSP A,JKP TRDP
1148:TRT1 A,JKP TRDP
1149:TRT2 A,JKP TRDP
1150:YK01 A,JKP TRDP
1151:CSRL A,JKP TRDP
1152:WDBS A,JKP TRDP
1153:WDHE A,JKP TRDP
1154:WDHO A,JKP TRDP
1155:WDHN A,JKP TRDP
1156:WDSN A,JKP TRDP
1157:WDSY A,JKP TRDP
1158:WDTN A,JKP TRDP
1159:WDWJ A,JKP TRDP

*

*

*

*HISTORY:

*

* 0.2 Data supporting Helpston link JLR 08/01/03 *

* 0.3 Mods to ET chains and CCTV hold berths JLR 12/01/03 *

- * 0.4 CCTV berth system ref. TREP & NDSD steps. Responding to test logs *
- * 02 - 52 as required *
- * 0.5 Add to berth clear ass. with ND steps, DUMMY berth added, maps *
- * altered to PE/Testing comments. Alarm berths TRAD & TRAX added. *
- * JK added to K786. Kings Dyke single letter code change. *
- * Modifications associated with STD ET chains. FAT Test log updates *
- * 0.6 Comment CN2 in header. DN01 TX as 0930. JK added to berths 0864 & *
- * 0804. SD26 & SD28 mods to characteristics. TDM alarm berths added. *
- * K769 & K771 received from KX as 9769 & 9771. DN01 now D001. *
- * DR01 & DR02 now DN01 & DN02. TEST berth added. Cambridge CIS now *
- * CA01. CSR S TX flag supported. CSR S flag now TX only. IPLK alarm *
- * berth. *
- * 1.0 Berth occ conditions on 0487 removed. *
- * 1.1 0617 local C/O. 0344 FFUS & FFUF copy mods. Hold step on 0485 *
- * 1.2 0344 FFUS & FFUF copy altered back to V1.0 *
- * 1.3 0485 ET conditions changed. Hold step on 0344 to FFUS & FFUF *
- * 1.4 0485 ET conditions changed again. Hold step removed from 0485 *
- * 1.5 New SSI inputs to PB TD. *
- * 1.6 Updates to test comments *
- * 3.0 Mod to fix Tx problem to St. James Deeping. *
- * 08/07/05 3.1 RSL Alarm berth WDWJ added for Werrington Jcn westcad link*
- * 22/09/05 V5.0 RSL INCORPORATION OF BI-DI DATA VERSIONS 4.1,4.2 AND V4.3*
- * INTO WERRINGTON TD V4.0 FOR PBORO BI-DI DATA *
- * 27/09/05 V5.1 RSL ALTERATIONS FOR BYTHAM/STOKE TDM REPLACEMENT(WESTCAD)*
- * 13/10/05 V5.2 RSL REMOVAL OF BI-DI DATA TO REFLECT BUILD BEFORE BI-DI *
- * 20/10/05 V6.0 RSL 0799/0800 STEPPING MOD REINSTATED, DATA TO FULL *
- * COMMISSIONING VERSION *

* 01/11/05 V7.0 RSL REBUILT FOR PBORO BI-DI SIGNALLING *

* 11/11/05 V7.1 RSL ALTERATIONS FOR HELPSTON AND TALLINGTON REPLACEMENT *

* (WESTCADS) *

* 06/12/05 V8.1 RSL ALTERATIONS FOR HOLME AND HUNTINGDON REPLACEMENT *

* (WESTCADS) *

* 19/12/05 V10.0 RSL ALTERATIONS FOR SANDY AND ST. NEOTS REPLACEMENT *

* (WESTCADS) *

* 06/01/06 V11.0 RSL REMOVAL OF TDMUX INPUTS AND ALARMS,TIDY UP OF *

* DONCASTER FRINGE *

* 07/12/13 V12.0 PB PETERBOROUGH STATION PLATFORM ENHANCEMENTS *

* 17/12/13 V12.1 PB SMART TO GET ALARM BERTHS. 0419 removed *

* 20/05/14 V12.3 KDE Step from P444 to P343 corrected *
